

<b>Document Title:</b> <b>Description, Using Apogee Oxygen Sensors with ZENTRA System Pages</b>		<b>Part #</b> <b>18476</b>	
		<b>Release Date:</b> <b>10.16.2020</b>	
<b>Rev</b>	<b>Description</b>	<b>Revision By</b>	<b>Date</b>
00	DCO 11361 Initial release tied to DFM Sheet 07393	LAJ	10.16.2020
01	Corrected mistakes when updating DCO for cover	CSC	9.10.2021
02	Corrected per <a href="#">DCO 12413</a>	CSC	9.28.2021

**Production File Path:** [http://publications.metergroup.com/Manuals/18476 Apogee SO-411 Print.pdf](http://publications.metergroup.com/Manuals/18476_Apogee_SO-411_Print.pdf)

**Working File Path:**

Google Drive\Shared drives\Product Number Library\18400-18499\18476

**Dimensions:** 12.5" wide x 8" tall (folded, 8"H x 6.25"W)

**Colors:** CMYK/Full color 4/4

**Printer Type:** Online or in house printer

**Sample image (scale not to actual size):**

18476-02  
9.28.2021

**TABLE OF CONTENTS**

1. Introduction.....	2
2. Installation.....	2
2.1 Connect to METER ZENTRA Series Logger.....	3
2.2 Sensor Calibration.....	4
2.3 Heater Power Supply.....	7
3. Data Interpretation.....	7
4. Troubleshooting.....	7
5. Customer Support.....	8
Index.....	10